



How to build your robot

www.pib.rocks/build



assembly instructions for:

ELBOW



You
Print
Build
Develop

your own robot!

Printable and pre-assembled parts



Pib's elbow consists of **12 printable parts** and is assembled in **16 steps**.

In order to construct the elbow, you will need to print the parts as seen in the table.

Please note: For better readability we use the abbreviations in the tutorial: C08 instead of C08-Central_rotator_bracket.

Printable parts

2 x **C08**-Central_rotator_bracket

C09-Central_rotator_connector

C10-Elbow

C11-Elbow_servo_scaffold

C12-Elbow_motor_connector

C13-Elbow_shell_lower_dorsal

C14-Elbow_shell_lower_medial


C15-Central_rotator_motor_connector

2 x **C16**-Elbow_joint_connector


C17-Elbow_motor_mount

Printable parts - Overview

C10-Elbow




C08-Central_rotator_bracket



C15-Central_rotator_motor_connector




C09-Central_rotator_connector




Printable parts - Overview


C13-Elbow_shell_lower_dorsal




C12-Elbow_motor_connector



C14-Elbow_shell_lower_medial



C16-Elbow_joint_connector



Printable parts - Overview

C11-Elbow_servo_scaffold



C17-Elbow_motor_mount



Non-printable parts



You will also need the following non-printable parts from our pib.Box Master.

If you do not have it yet, you can buy in our shop <https://shop.pib.rocks>.

Non-printable parts

1 x **E07** MG996R Servo

1 x **E09** DS3225 Servo

1 x **M09** Motor_clamp

1 x **M15** Nylon-motor-connector

Non-printable parts

34 x **S01** M3 nuts

2 x **S03** M3 8 mm screws

17 x **S04** M3 10 mm screws

8 x **S05** M3 12 mm screws

3x **S05** M3 16 mm screws

4 x **S08** M3 20 mm screws

2 x **M08** 20 mm metal rods

2 x **M03** medium sized ballbearings (10 x 19 x 7mm)

2 x **M06** Ballbearing_Axial (70x50x3)

2 x **M07** Thrust_Bearing (70x50x1)

1 x **M12** T700 Spring

Build it better: our suggestion for assembling pib



We recommend **tools** for each step. These are a suggestion, you can of course also use other tools.



1-5



We have categorized each step according to its **difficulty** - from **1-5** (1 being the easiest, 5 the hardest)



We also show you which **non-printable parts** you need for each step

Step 1


Place **14 x nuts** in the shown spots in **C11**.




Our tip: use a small screwdriver or a precision tool to put the nuts into the holes and hit it gently with a hammer to place it correctly.

Step 2

Place **1 x E07** inside **C11** and use **4 x 10 mm** screws to hold it.




Pull the cable first, then tilt the motor a little bit to put in into the shown spot. You may apply some gently force.




Step 3a

Connect **M15** to **E07**.



Step 3b



Insert **4 x nuts** in the shown spot of **C08**.



Our tip: use a small screwdriver or a precision tool to put the nuts into the holes and hit it gently with a hammer to place it correctly.



Step 3c

Place **C08** on top of **C11**.



Step 3d

Place **M06** and then **M07** on top of **C08**.



Please make sure, that the small movable pieces in M06 face towards M07.

Step 4a

Insert **2 x nuts** in **C15**.



1





2x



Step 4b

Flip **C15** and connect it to **M15** using **1 x 10mm screw**.




Please make sure, that you connect C15 in the shown orientation.


Step 5

Insert **2 x nuts** in **C09**.

Connect **C09** to **C15** using **2 x 8 mm screws**.




Please make sure, that you connect C09 to C15 in the shown orientation.




Step 6a

Place **M07** and **M06** on top of **C09**.




Please make sure, that the small movable pieces in M06 face towards M07.



Step 6b

Insert **4 x nuts** in the shown spot of **C08**.



(This step is identical to step 3b – we need the part C08 twice in pib ´s elbow.)



Our tip: use a small screwdriver or a precision tool to put the nuts into the holes and hit it gently with a hammer to place it correctly.



Step 6c

Flip **C08** and put it on top of the assembly.



Step 7a

Use **4 x 12 mm screws** (for the lower 4 holes of C14) to connect **C14** to the assembly.





Step 7b

Use **4 x 10 mm screws** (for the upper 4 holes of C14) to connect **C14** to the assembly.





4 x 10mm screws





Step 8a

Use **4 x 12 mm screws** (for the upper 4 holes of C13) to connect **C13** to the assembly.



Step 8b



Use **4 x 10 mm screws** (for the upper 4 holes of C13) to connect **C13** to the assembly.



Step 9


Place **2 x nuts** in **C12**.

Flip the previous assembly and then connect **C12 to C11** using **2 x 16 mm screws**.



Step 10


Insert **2 x nuts** and **2 x M03 ball bearings** in the shown spots in **C10**.



You may need to apply gentle force to put the ballbearings in the shown spots.


Step 11a

Insert **4 x nuts** in **C17**.



Step 11b

Place **1 x E09 servo** in the shown spot of **C17** and fix it using **4 x 10 mm screws**.





Pull the cable first, then tilt the motor a little bit to put in into the shown spot. You may apply some gently force.




Step 12

Connect **C17** to **C10** with 2 x 20 mm screws.



Step 13



Attach **1 x M09 motorclamp** to the E09 servo and tighten it using the 2 small screws in the clamp.



M09 motorclamp

Step 14 - note


Now we can connect both previous assemblies together.



Step 14a




Connect the lower part of the elbow to the upper part of the elbow by sliding **M09 motorclamp** into **C12**.





Please note: the motor is hidden in the second picture for better visibility.

You may need to apply some gentle force to put M09 into C12.





Step 14b

Connect **C12** and **C11** by using **1 x 16mm screw**.





Step 15

Use **2 x C16** and **2 x 20mm screws** to connect the lower and upper part of the elbow.



Step 16


Attach **1 x M12 spring** to C10 and C11 and use **2 x M08 rods** to fix it.



Congratulations

You did a great job, pib´s elbow is assembled!

Well done!



Do you need support?



Or do you need our pib.Box with all non-printable parts?

Or maybe you have some new ideas and improvements?

Please contact us.



team@pib.rocks

Send us an email.



discord.com/invite/GRdpyeDu7P

Join us on Discord.



shop.pib.rocks

Order non-printable parts for pib.