



How to build your robot

www.pib.rocks/build



Instructions for:

MOTOR CALIBRATION



You
Print
Build
Develop

your own robot!

Important note



In order to use the motors for pib's movement it is important to **calibrate** them before building them into pib.

Pib has two different motors build in, in total **14** and **25** if 2 arms. They can be calibrated in the same way.

For this tutorial you will need the shown parts from the table. Additionally, we suggest to first build **pib's head** and install the **software to the Raspberry Pi** as you will need to use this for the calibration.

You can find the tutorials here:

<https://pib.rocks/build/how-to-build-pibs-head/>

<https://pib.rocks/build/how-to-install-raspberry-pi/>

Non-printable parts

10 x **E07**-MG996R

2 x **E09**-DS225

3 x **E15**-DS5180SSG

1 x **E13**-SPL-82

1 x **E14**-Power_Supply-cable


1 x **E03**-TinkerForge ServoBricklet 2.0

1 x **Bricklet cable**

10 cm (red-black) **power cable**

Step 0

Make sure **all motors** in are calibrated according to this tutorial



Step 1a



Connect output jack of **E14 power supply** into **E20 power jack**, Cut 10 cms from red and black wires, strip both ends insert **wires** on the other side of the jack



Step 1b





Pull the red and blue switches in **E13** (T-Connector), insert wires coming out of power supply jack and then close them.



Make sure to place the wires in the correct switches:


- ✓ **Red** wire to **red** switch
- ✓ **Black** wire to **blue** switch





Step 2

Connect the raspberry pi power supply with the type-C connector to the extension cable to type-C port in raspberry Pi

E01 - Raspberry Pi 5



Type C cable from charger to type C port of Raspberry Pi



Wire is highlighted in **yellow** but its original color is **black**

E16 - Raspberry Pi power brick 5V


Step 3a

Cut **10 cm** of the red-black **power cable** and insert them to the **E03 TinkerForge ServoBricklet**.



Make sure to place the wires in the correct switches:

- ✓ **Red** wire to **+ Symbol** (left spot)
- ✓ **Black** wire to **- Symbol** (right spot)




Step 3b

Now you can insert the cables to the T-Connector.



Make sure to place the wires in the correct switches:

- ✓ **Red** wire to **red** switch
- ✓ **Black** wire to **blue** switch



Step 4




Now, we can connect the motors to the ServoBricklet.

Please note that only 2 motors are connected for illustration but you should calibrate all motors, You can add 10 motors at the same time - there are 10 slots for motors on the ServoBricklet



It is also important to have the correct orientation here:

- ✓ **Yellow** cable to **S Symbol**
- ✓ **Orange** cable to **+ Symbol**
- ✓ **Brown** cable to **- Symbol**




Step 5

Connect the **bricklet cable** to the **TinkerForge HAT** in the head and then to the **TinkerForge ServoBricklet**.

Please note that the Tinkerforge Hat doesn't need extra power connection it is only connected via GPIO as in head tutorial





Use slot A



Step 6



Plug the power cable into the power supply and start Raspberry Pi OS. - **turn on pi**
Open the **Brick viewer** application.



Step 7



Click **"Connect"** and navigate to the tab **"Servo Bricklet 2.0"**



Step 8


Select "**All Servos**" and change the values as shown.

Other values are not important and do not need to be changed.

You will hear a sound from the motors once you changed the values – that is the calibration! The motors have switched to a 0-Position!

Select "All Servos"

Click on enable to power motors



Setup ✱ Master Brick 3.1 ✱ Servo Bricklet 2.0 ✱
 UID: SyW FW Version: 2.0.0 ✱ Update Timeouts: 0 Status LED: Show Status ▼ Reset More

All Servos ▼ Enable


Current Consumption: 0mA
 Pulse Width min/max (µs): 700 / 2500
 Degree min/max (°/100): -9000 / 9000

Position (°/100)	Velocity (°/100s)	Acceleration (°/100s ²)	Deceleration (°/100s ²)	Period (µs)
0	100000	50000	50000	19500

Input Voltage: 0V
 Ena Pos Vel Cur
 0 On
 1 On
 2 On
 3 On
 4 On
 5 On
 6 On
 7 On
 8 On
 9 On

Step 8

For 1 **E15-DS5180SSG** that will be used in elbow, set it to **5500** not to **0** position
 (if you are using a 2 arm pib you will need to calibrate 2 of these motors)



Click on enable to power motors

Brick Viewer 2.4.22

Setup Master Brick 3.1 Servo Bricklet 2.0

UID: SyW FW Version: 2.0.0 Update Timeouts: 0 Status LED: Show Status Reset More

Servo 8 Enable

Current Consumption: 0mA

Pulse Width min/max (µs): 700 / 2500

Degree min/max (°/100): -9000 / 9000

Position (°/100)	Velocity (°/100s)	Acceleration (°/100s ²)	Deceleration (°/100s ²)	Period (µs)
5500	100000	50000	50000	19500

Input Voltage: 0V

Ena	Pos	Vel	Cur
0	Off	⊖	
1	Off	⊖	
2	Off	⊖	
3	Off	⊖	
4	Off	⊖	
5	Off	⊖	
6	Off	⊖	
7	Off	⊖	
8	On	⊕	
9	Off	⊖	

Congratulations

Remove the calibrated motors, connect the remaining motors and repeat step 6-8, until you have calibrated **all motors**

Once finished, you can disassemble most parts as you will need the T-Connector, bricklet cable, motors and so on in the other tutorials.

Well done!



Do you need support?



Or do you need our pib.Box with all non-printable parts?
Or maybe you have some new ideas and improvements?
Please contact us.



team@pib.rocks
Send us an email.



discord.com/invite/GRdpYeDu7P
Join us on Discord.



shop.pib.rocks
Order non-printable parts for pib.